Product Change Notification

PCN No: 2007-10-02-01
Report Date: October 2, 2007
Subject: GLK19264-7T-1U and GLK19264-7T-1U-USB New Firmware Version Release

List of New / Changed Products:

All the following Graphic displays (and their variants):

GLK19264-7T-1U	GLK19264-7T-1U-USB	

Reason for Change:

A bug fix on the control of the top LED (LED 1) resulting to a firmware upgrade.

Product Change:

The following list of firmware changes are all effective on all the variants of the graphic displays as stated under 'List of New / Changed Products'.

Firmware Changes:

Display	New Firmware Version
GLK19264-7T-1U	v5.8
GLK19264-7T-1U-USB	v5.8

New Released Firmware (released October 2, 2007):

1) In version v5.7 (previously released version), the top LED (LED 1) unconditionally reverts to yellow state / colour whenever a key is pressed (starting state / colour does not matter). This has now been fixed. LED 1, like the other LEDs are now not affected by any activities done on the keypad.

Documentation Revision

Revision	Changes	Date	Author
1.0	Initial Release	October 2/07	R Malinis

Contact Information:

Clare Wagner (Sales Manager): cwagner@matrixorbital.ca

Reference Documents/Attachments:

Location: http://www.matrixorbital.ca/manuals/

Approvals:

Engineering: **Larry Grieve (Engineering Coordinator)**

Sales: **Clare Wagner (Sales Manager)**

Production: **Mike McTavish (Production Manager)**