



Product Change Notification

PCN No: 2007-05-01-01

Report Date: May 1, 2007

Subject: GLK12232-25-SM Backlight Life

Reason for Change:

The GLK12232-25-SM requires a change on the resistor used for the backlight LED on the display to prolong backlight life.

Product Change:



Here is the current backlight resistor values for the following displays:

GLK12232-25-SM PCB Rev 1.4 (-GW and -WB): 75 Ohms

GLK12232-25-SM-V PCB Rev 1.4 (-GW and -WB): 61.9 Ohms

Here is the new backlight resistor values:

GLK12232-25-SM PCB Rev 1.4 (-GW and -WB): 130 Ohms

GLK12232-25-SM-V PCB Rev 1.4 (-GW and -WB): 91 Ohms

Because of these changes, customers will experience some comparative dimness in the display but can expect longer lasting backlight life.

Schedule of Change: This change will commence immediately.

Contact Information:

Adam Lintott (Sales Manager): alintott@matrixorbital.ca

Reference Documents/Attachments:

Location: <http://www.matrixorbital.ca/manuals/>

Approvals:

<i>Documentation / Tech Support</i>	<i>Engineer</i>	<i>Engineer</i>	<i>Production</i>	<i>Sales</i>
Larry Grieve	Larry Grieve	James McTavish	Mike McTavish	Adam Lintott